CSMS Vehicle Maintenance BASIC Violations				
Section	Violation Description Shown on Roadside Inspection	Group	Weight	
365.511	Fail to display current CVSA Decal: Permanent Authority	Inspection Reports	4	
374.313(a)	Failure to maintain a reasonable temperature	Cab, Body, Frame	2	
374.313(b)	Bus — Failure to maintain restroom	Cab, Body, Frame	2	
374.313(c)	Bus — Not maintained in clean working order	Cab, Body, Frame	2	
385.103(c)	Fail to display current CVSA decal—Provisional Authority	Inspection Reports	4	
392.22(b)	Failing/improper placement of warning devices	Cab, Body, Frame	2	
392.33	Operating CMV with lamps/reflectors obscured	Lighting	6	
392.7	No pre-trip inspection	Inspection Reports	4	
392.8	Failing to inspect/use emergency equipment	Emergency Equipment	2	
393.11	No/defective lighting devices/reflective devices/projected	Lighting	6	
	No retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993, No reflective			
393.11(b)	material on rear or side	Reflective Sheeting	3	
373111(3)	Side retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993 (does not meet	remedite emeeting		
393.11(b)(1)	50% as required)	Reflective Sheeting	3	
393.11(b)(2)	Lower retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.11(b)(3)	Upper retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
	Truck Tractor Lower mud flap retroreflective sheeting/reflex reflectors manufactured on or after 7/1/1997	Reflective Sheeting		
393.11(c)(1)		Kenecuve sneeting	3	
393.11(c)(2)	Truck Tractor Upper body corners retroreflective sheeting/reflex reflectors manufactured on or after 7/1/1997	Reflective Sheeting	3	
393.11LR	Lower retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.11N	No retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.11RT	Retroreflective not affixed as required. Trailer manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.11S	Side retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.11TL	Truck Tractor manufactured on or after 7/1/1997 with no retro reflective sheeting or reflex reflectors on mud flaps	Reflective Sheeting	3	
000 4 4777		j		
393.11TT	Truck Tractor no retroreflective sheeting/reflex reflectors manufactured on or after 7/1/1997	Reflective Sheeting	3	
393.11TU	Truck Tractor upper body corners retroreflective sheeting/reflex manufactured on or after 7/1/1997	Reflective Sheeting	3	
	Upper reflex reflectors retroreflective sheeting/reflex reflectors manufactured on or after			
393.11UR	12/1/1993	Reflective Sheeting	3	
393.13(a)	Retroreflective tape not affixed; Trailer manufactured before 12//1/1993	Reflective Sheeting	3	
393.13(b)	No retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.13(c)(1)	Side retroreflective sheeting/reflex reflectors manufactured on or before 12/1/1993	Reflective Sheeting	3	
393.13(c)(2)	Lower retroreflective sheeting/reflex reflectors manufactured on or before 12/1/1993	Reflective Sheeting	3	
393.13(c)(3)	Upper retroreflective sheeting/reflex reflectors manufactured on or before 12/1/1993	Reflective Sheeting	3	
393.13(d)(1)	Side retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.13(d)(2)	Lower rear retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.13(d)(3)	Upper rear retroreflective sheeting/reflex reflectors manufactured on or after 12/1/1993	Reflective Sheeting	3	
393.17	No/defective lamp/reflector-towaway operation	Lighting	6	
393.17(a)	No/defective lamps-towing unit-towaway operation	Lighting	6	
393.17(b)	No/defective towaway lamps on rear unit	Lighting	6	
393.19	Inoperative/defective hazard warning lamp	Lighting	6	
393.201(a)	Frame cracked / loose / sagging / broken	Cab, Body, Frame	2	
393.201(b)	Bolts securing cab broken/loose/missing	Cab, Body, Frame	2	
393.201(c)	Frame rail flange improperly bent/cut/notched	Cab, Body, Frame	2	
393.201(d)	Frame accessories improperly attached	Cab, Body, Frame	2	
393.201(e)	Prohibited holes drilled in frame rail flange	Cab, Body, Frame	2	
393.203	Cab/body parts requirements violations	Cab, Body, Frame	2	
		, ,,	2	

CSMS Vehicle Maintenance BASIC Violations				
Section	Violation Description Shown on Roadside Inspection	Group	Weight	
393.203(b)	Cab/body improperly secured to frame	Cab, Body, Frame	2	
393.203(c)	Hood not securely fastened	Cab, Body, Frame	2	
393.203(d)	Cab seats not securely mounted	Cab, Body, Frame	2	
393.203(e)	Cab front bumper missing/ unsecured/ protrude	Cab, Body, Frame	2	
393.205(a)	Wheel/rim cracked or broken	Wheels, Studs, Clamps, Etc.	2	
393.205(b)	Stud/bolt holes elongated on wheels	Wheels, Studs, Clamps, Etc.	2	
393.205(c)	Wheel fasteners loose and/or missing	Wheels, Studs, Clamps, Etc.	2	
393.207(a)	Axle positioning parts defective/missing	Suspension	7	
393.207(b)	Adjustable axle locking pin missing/disengaged	Suspension	7	
393.207(c)	Leaf spring assembly defective/missing	Suspension	7	
393.207(d)	Coil spring cracked and/or broken	Suspension	7	
393.207(e)	Torsion bar cracked and/or broken	Suspension	7	
393.207(f)	Air suspension pressure loss	Suspension	7	
393.207(g)	No/defective air suspension exhaust control	Suspension	7	
393.209(a)	Steering wheel not secured/broken	Steering Mechanism	(
393.209(b)	Excessive steering wheel lash	Steering Mechanism	(
393.209(c)	Loose steering column	Steering Mechanism	(
393.209(d)	Steering system components worn/welded/missing	Steering Mechanism	(
393.209(e)	Power steering violations	Steering Mechanism	(
373.207(c)	Tower steering violations	Clearance Identification		
393.23	Required lamp not powered by vehicle electricity	Lamps/Other		
393.24(a)	Non-compliance with headlamp requirements	Lighting	2	
. ,	Non-compliant fog/driving lamps	Lighting		
393.24(b) 393.24(c)	Improper headlamp mounting	Lighting Lighting	6	
	1 1 0	0 0	(
393.24(d)	Improper head / auxiliary / fog lamp aiming	Lighting	6	
393.25(a)	Improper lamp mounting	Lighting	6	
393.25(b)	Lamps are not visible as required	Lighting	(
393.25(e)	Lamp not steady burning	Lighting	(
393.25(f)	Stop lamp violations	Lighting	(
393.26	Requirements for reflectors	Lighting	(
393.28	Improper or no wiring protection as required	Other Vehicle Defect	3	
393.30	Improper battery installation	Other Vehicle Defect	3	
393.40	Inadequate brake system on a CMV	Brakes, All Others	4	
393.40(a)	Inadequate brake system	Brakes, All Others	4	
393.41	No or defective parking brake system on CMV	Brakes, All Others	4	
393.41(a)	Inadequate brake system	Brakes, All Others	4	
393.42	No brakes as required	Brakes, All Others	4	
393.42(a)	No brakes on all wheels as required	Brakes, All Others	4	
393.43	No/improper breakaway or emergency braking	Brakes, All Others	4	
393.43(a)	No/improper tractor protection valve	Brakes, All Others	4	
393.43(b)	Towing vehicle unable to actuate trailer brakes with reduced air	Brakes, All Others	4	
393.43(d)	No or defective automatic trailer brake	Brakes, All Others	4	
393.44	No/defective bus front brake line protection	Brakes, All Others	4	
393.45	Brake tubing and hose adequacy	Brakes, All Others	4	
393.45(a)(4)	Failing to secure brake hose/tubing against mechanical damage	Brakes, All Others	4	
393.45(b)(2)	Failing to secure brake hose/tubing against mechanical damage	Brakes, All Others	4	
393.45(b)(3)	Failing to secure brake hose/tubing against high temperatures	Brakes, All Others	4	
393.45(d)	Brake connections with leaks/constrictions	Brakes, All Others	4	

	CSMS Vehicle Maintenance BASIC Violations				
Section	Violation Description Shown on Roadside Inspection	Group	Weight		
393.47	Inadequate/contaminated brake linings	Brakes, All Others	4		
393.47(a)	Inadequate brakes for safe stopping	Brakes, All Others	4		
393.47(b)	Mismatched brake chambers on same axle	Brakes, All Others	4		
393.47(c)	Mismatched slack adjuster effective length	Brakes, All Others	4		
393.47(d)	Insufficient brake linings	Brakes, All Others	4		
393.47(e)	Clamp/Roto-Chamber type brake(s) out of adjustment	Brakes Out of Adjustment	4		
()	1' /1 //	,			
393.47(f)	Wedge type brake(s) out of adjustment	Brakes Out of Adjustment	4		
393.47(g)	Insufficient drum/rotor thickness	Brakes, All Others	4		
393.48(a)	Inoperative/defective brakes	Brakes, All Others	4		
393.48(b)(1)	Defective brake limiting device	Brakes, All Others	4		
393.50	Inadequate reservoir for air/vacuum brakes	Brakes, All Others	4		
393.50(a)	Failing to have sufficient air/vacuum reserve	Brakes, All Others	4		
393.50(b)	Failing to equip vehicle—prevent reservoir air/vacuum leak	Brakes, All Others	4		
393.50(c)	No means to ensure operable check valve	Brakes, All Others	4		
393.50(d)	No or defective air reservoir drain valve	Brakes, All Others	4		
393.51	No or defective brake warning device	Brakes, All Others	4		
393.51(a)	Failing to equip brake system with warning device or gauge	Brakes, All Others	4		
393.51(c)	Failing to equip brake system with warning device or gauge	Brakes, All Others	4		
393.52(a)(1)	Insufficient braking force as percent of GVW or GCW	Brakes, All Others	4		
393.53(a)	Automatic brake adjuster CMV manufactured on or after 10/20/1993— hydraulic brake	Brakes, All Others	4		
393.53(b)	Automatic brake adjuster CMV manufactured on or after 10/20/1994— air brake	Brakes, All Others	4		
373.33(b)	Brake adjustment indicator CMV manufactured on or after 10/20/1994— external automatic	Brakes, 1111 Outers	'		
393.53(c)	adjustment	Brakes, All Others			
393.55(a)	ABS— all CMVs manufactured on or after 3/1/1999 with hydraulic brakes	Brakes, All Others	4		
393.55(b)	ABS— malfunction indicators for hydraulic brake system	Brakes, All Others	4		
393.55(c)(1)	ABS— all tractors manufactured on or after 3/1/1997 air brake system	Brakes, All Others	4		
393.55(c)(1)	ABS— all other CMVs manufactured on or after 3/1/1998 air brake system	Brakes, All Others	4		
373.33(C)(Z)	ABS— malfunctioning circuit/signal manufactured on or after 3/1/1997, single-unit CMV	Diakes, All Others	7		
393.55(d)(1)	manufactured on or after 3/1/1998	Brakes, All Others	4		
373.33(d)(1)	mandractured on or after 3/1/1776	Diakes, All Others	7		
393.55(d)(2)	ABS— malfunctioning indicator to cab of towing CMV manufactured on or after 3/1/2001	Brakes, All Others	4		
393.33(d)(2)		Drakes, All Others	4		
393.55(d)(3)	ABS— malfunctioning indicator connection from towed CMV manufactured on or after 3/1/2001	Brakes, All Others	4		
373.33(d)(3)	ABS— malfunctioning lamps towed CMV manufactured on or after 3/1/1998, manufactured	Brakes, 7th Others	7		
393.55(e)	before 3/1/2009	Brakes, All Others	1		
373.33(C)	before 3/1/2007	Windshield /Glass	4		
393.60(b)	Windshields required	/Markings	1		
393.00(b)	windshields required		1		
393.60(c)	Damaged or discolored windshield	Windshield /Glass /Markings	1		
393.00(C)	Daniaged of discolored windshield		1		
393.60(d)	Claring normita loss than 70 normant of light	Windshield /Glass /Markings	1		
393.00(d)	Glazing permits less than 70 percent of light		1		
303 61	Inadequate or missing truck side windows	Windshield /Glass /Markings	1		
393.61	madequate of missing fruck side willdows		1		
202 (1/-)	In decreate or missing totals aid windows	Windshield / Glass	1		
393.61(a)	Inadequate or missing truck side windows	/Markings	1		
202 (1/L)	Process windows accome in an arctive /-1-tt1	Windshield / Glass	4		
393.61(b)	Buses-window escape inoperative/obstructed	/Markings	1		
202 (14) (2)	Encourage and anis described and the books	Windshield /Glass	4		
393.61(b)(2)	Emergency exit window handle broken	/Markings	1		

CSMS Vehicle Maintenance BASIC Violations				
Section	Violation Description Shown on Roadside Inspection	Group	Weight	
		Windshield /Glass		
393.61(c)	Buses-push out window requirements violation	/Markings	1	
		Windshield /Glass		
393.62(a)	No or defective bus emergency exits, manufactured on or after 9/1/1994	/Markings	1	
		Windshield /Glass		
393.62(b)	No or defective bus emergency exits, manufactured on or after 9/1/1973 but before 9/1/1994	/Markings	1	
		Windshield /Glass		
393.62(c)	No or defective bus emergency exit windows, manufactured before 9/1/1973	/Markings	1	
		Windshield /Glass		
393.62(d)	No / defective Safety glass/push-out window	/Markings	1	
		Windshield /Glass		
393.62(e)	No or inadequate bus emergency exit marking	/Markings	1	
393.65	Fuel system requirements not met	Fuel Systems	1	
393.65(a)	Fuel system requirements not met	Fuel Systems	1	
393.65(b)	Improper location of fuel system	Fuel Systems	1	
393.65(c)	Improper securement of fuel tank	Fuel Systems	1	
393.65(f)	Improper fuel line protection	Fuel Systems	1	
393.67	Fuel tank requirement violations	Fuel Systems	1	
393.67	Fuel tank requirement violations	Fuel Systems	1	
393.67(c)(7)	Fuel tank fill pipe cap missing	Fuel Systems	1	
393.67(c)(8)	Improper fuel tank safety vent	Fuel Systems	1	
393.67(d)	Failing to equip vehicle with fuel tank free of leaks	Fuel Systems	1	
393.68	Compressed Natural Gas (CNG) Fuel Container does not conform to regulations	Other Vehicle Defect	3	
393.70	Fifth wheel	Coupling Devices	3	
393.70(a)	Defective coupling device—improper tracking	Coupling Devices	3	
393.70(b)	Defective/improper fifth wheel assemblies	Coupling Devices	3	
393.70(b)(2)	Defective fifth wheel locking mechanism	Coupling Devices	3	
393.70(c)	Defective coupling devices for full trailer	Coupling Devices	3	
393.70(d)	No/improper safety chains/cables for full trailer	Coupling Devices	3	
393.70(d)(8)	Improper safety chain attachment	Coupling Devices	3	
393.71	Improper coupling driveaway/towaway operation	Coupling Devices	3	
393.71(g)	Prohibited towing connection / device	Coupling Devices	3	
393.71(h)	Towbar requirement violations	Coupling Devices	3	
393.71(h)(10)	No/improper safety chains/cables for towbar	Coupling Devices	3	
393.75	Tires/tubes (general)	Tires	8	
393.75(a)	Flat tire or fabric exposed	Tires	3	
393.75(a)(1)	Tire—ply or belt material exposed	Tires	8	
393.75(a)(2)	Tire—tread and/or sidewall separation	Tires	3	
393.75(a)(3)	Tire—flat and/or audible air leak	Tires	3	
393.75(a)(4)	Tire—cut exposing ply and/or belt material	Tires	3	
393.75(b)	Tire—front tread depth less than 4/32 of inch	Tires	3	
393.75(c)	Tire—other tread depth less than 2/32 of inch	Tires	3	
393.75(d)	Tire-bus regrooved/recap on front wheel	Tires	3	
393.75(e)	Tire—regrooved on front of truck/truck-tractor	Tire vs. Load	3	
393.75(f)	Tire—load weight rating/under inflated	Tire vs. Load	3	
393.75(f)(1)	Weight carried exceeds tire load limit	Tire vs. Load	3	
393.75(f)(2)	Tire under-inflated	Tire vs. Load	3	
393.75(h)	Tire under-inflated	Tire vs. Load	3	
393.76	Sleeper berth requirement violations	Other Vehicle Defect	3	
393.76(b)(1)	Sleeper berth location	Other Vehicle Defect	3	
393.76(b)(2)	Sleeper berth location	Other Vehicle Defect	3	

CSMS Vehicle Maintenance BASIC Violations			
Section	Violation Description Shown on Roadside Inspection	Group	Weight
393.76(h)	Using a sleeper berth that is not equipped with occupant restraint	Cab, Body, Frame	2
393.77	Defective and/or prohibited heaters	Other Vehicle Defect	3
393.77(b)(11)	Bus heater fuel tank location	Other Vehicle Defect	3
393.77(b)(5)	Protection of operating controls from tampering	Other Vehicle Defect	3
		Windshield /Glass	
393.78	Windshield wipers inoperative/defective	/Markings	1
		Windshield /Glass	
393.78(a)	Windshield wipers inoperative/defective	/Markings	1
		Windshield /Glass	
393.79	Defroster / Defogger inoperative	/Markings	1
		Windshield /Glass	
393.79(a)	Defroster / Defogger inoperative	/Markings	1
393.80	Failing to equip vehicle with two rear vision mirrors	Other Vehicle Defect	3
393.80(a)	Failing to equip vehicle with two rear vision mirrors	Other Vehicle Defect	3
393.81	Horn inoperative	Other Vehicle Defect	3
393.82	Speedometer inoperative / inadequate	Other Vehicle Defect	3
393.83(a)	Exhaust system location	Exhaust Discharge	1
393.83(b)	Exhaust discharge fuel tank/filler tube	Exhaust Discharge	1
393.83(c)	Improper exhaust—bus (gasoline)	Exhaust Discharge	1
393.83(d)	Improper exhaust—bus (diesel)	Exhaust Discharge	1
393.83(d)(1)	Non-gas-powered bus exhaust discharging greater than 15 inches forward of rear	Exhaust Discharge	1
393.83(e)	Improper exhaust discharge (not rear of cab)	Exhaust Discharge	1
393.83(f)	Improper exhaust system repair (patch/wrap)	Exhaust Discharge	1
393.83(g)	Exhaust leak under truck cab and/or sleeper	Exhaust Discharge	1
393.83(h)	Exhaust system not securely fastened	Exhaust Discharge	1
393.84	Inadequate floor condition	Cab, Body, Frame	2
393.86	No or improper rearend protection	Cab, Body, Frame	2
393.86(a)(1)	Rear impact guards—all trailers/semitrailers manufactured on or after 1/26/98	Cab, Body, Frame	2
393.86(a)(2)	Impact guard width— all trailers/semitrailers manufactured on or after 1/26/98	Cab, Body, Frame	2
393.86(a)(3)	Impact guard height— all trailers/semitrailers manufactured on or after 1/26/98	Cab, Body, Frame	2
393.86(a)(4)	Impact guard rear— all trailers/semitrailers manufactured on or after 1/26/98	Cab, Body, Frame	2
(.)(.)		,,	
393.86(a)(5)	Cross-sectional vertical height— all trailers/semitrailers manufactured on or after 1/26/98	Cab, Body, Frame	2
(/ (/		, , ,	
393.86(b)(1)	Rear Impact Guards— motor vehicle manufactured on or after 12/31/52, see exceptions	Cab, Body, Frame	2
393.88	Improperly located television receiver	Cab, Body, Frame	2
393.89	Bus driveshaft not properly protected	Cab, Body, Frame	2
	1 1 71	Clearance Identification	
393.9(a)	Inoperative required lamps	Lamps/Other	2
393.90	Bus—no or obscure standee line	Cab, Body, Frame	2
393.91	Bus—improper aisle seats	Cab, Body, Frame	2
393.93(a)	Bus—not equipped with seat belt	Cab, Body, Frame	2
393.93(a)(3)	Seats not secured in conformance with FMVSS	Cab, Body, Frame	2
393.93(b)	Truck not equipped with seat belt	Cab, Body, Frame	2
393.95(a)	No/discharged/unsecured fire extinguisher	Emergency Equipment	2
393.95(a) (1)(ii)		Emergency Equipment	2
393.95(a)(1)(i)	No/discharged/unsecured fire extinguisher	Emergency Equipment	2
393.95(b)	No spare fuses as required	Emergency Equipment	2
393.95(c)	Spare fuses not as required	Emergency Equipment	2
393.95(f)	No / insufficient warning devices	Emergency Equipment	2
- / - / - / - /	Emergency warning devices not as required	Emergency Equipment	2

CSMS Vehicle Maintenance BASIC Violations			
Section	Violation Description Shown on Roadside Inspection	Group	Weight
393.95(g)	HM—restricted emergency warning device	Emergency Equipment	2
393.9H	Inoperative head lamps	Lighting	6
393.9T	Inoperative tail lamp	Lighting	6
393.9TS	Inoperative turn signal	Lighting	6
396.1	Must have knowledge of and comply with regulations	Inspection Reports	4
396.11	No or inadequate driver vehicle inspection report	Inspection Reports	4
396.11(a)(1)	No or inadequate driver vehicle inspection report	Inspection Reports	4
396.11(b)	Failing to ensure inspection report is complete and accurate	Inspection Reports	4
396.11(c)	Failing to correct safety defects reported by driver	Inspection Reports	4
396.11(c)(1)	Failing to certify that repairs were made or were not necessary	Inspection Reports	4
396.11(c)(2)	Failing to retain vehicle inspection reports for at least 3 months	Inspection Reports	4
396.13(a)	Driver inspection	Inspection Reports	4
396.13(b)	Driver inspection	Inspection Reports	4
396.13(c)	No reviewing driver's signature on Driver Vehicle Inspection Report (DVIR)	Inspection Reports	4
396.17(a)	Using a CMV not periodically inspected	Inspection Reports	4
396.17(b)	Using a CMV not periodically inspected	Inspection Reports	4
396.17(c)	Operating a CMV without periodic inspection	Inspection Reports	4
396.17(g)	Failing to repair parts not meeting inspection standards	Other Vehicle Defect	3
396.21(a)(1)	Failing to prepare inspection report in correct form and manner	Inspection Reports	4
396.21(a)(3)	Failing to prepare inspection report in correct form and manner	Inspection Reports	4
396.21(a)(4)	Failing to prepare inspection report in correct form and manner	Inspection Reports	4
396.21(a)(5)	Failing to prepare inspection report in correct form and manner	Inspection Reports	4
396.21(a)(6)	Failing to prepare inspection report in correct form and manner	Inspection Reports	4
396.21(b)(1)	Failing to retain periodic inspection report for 14 months	Inspection Reports	4
396.23(b)(1)	Failure to comply with mandatory State inspection program	Inspection Reports	4
396.25(a)	Failing to ensure all maintenance on a CMV meets minimum. standards	Brakes, All Others	4
(4)		Wheels, Studs, Clamps,	<u>'</u>
396.3(a)(1)	Inspection/repair and maintenance parts and accessories	Etc.	2
		Windshield /Glass	
396.3(a)(2)	Failing to inspect pushout windows every 90 days	/Markings	1
396.3A1B	Brakes (general)	Brakes, All Others	4
3,0,01112	Prince (general)	Brunes, The Guiero	'
396.3A1BA	Brake out of adjustment	Brakes Out of Adjustment	4
396.3A1BC	Brake-air compressor violation	Brakes, All Others	4
396.3A1BD	Brake-defective brake drum	Brakes, All Others	4
396.3A1BL	Brake-reserve system pressure loss	Brakes, All Others	4
396.3A1T	Tires (general)	Tires	8
396.5	Excessive oil leaks	Other Vehicle Defect	3
396.5(a)	Failing to ensure that vehicle is properly lubricated	Other Vehicle Defect	3
396.5(b)	Oil and/or grease leak	Other Vehicle Defect	3
396.7	Unsafe operations forbidden	Other Vehicle Defect	3
396.7(a)	Unsafe operations forbidden	Other Vehicle Defect	3
396.9(c)	Operating an Out-Of-Service (OOS) vehicle	Vehicle Jumping OOS	10
396.9(c)(2)	Operating an OOS vehicle	Vehicle Jumping OOS Vehicle Jumping OOS	10
396.9(d)(2)	Failure to correct defects noted on inspection report	Inspection Reports	4
396.9(d)(3)	Failure to return inspection report within 15 days	Inspection Reports	4
398.5	Parts/access—migrant workers	Other Vehicle Defect	3
398.5(a)	Parts/access—migrant workers	Other Vehicle Defect	3
398.7	Inspect/maintain motor vehicle—migrant workers	Inspection Reports	4
399.207	Vehicle access requirements violations	Cab, Body, Frame	2
399.207	Inadequate maintenance of driver access	Cab, Body, Frame	2
J77.411	madequate maintenance of univer access	Cab, Body, Frame	